



PARK SPRING DRIVE

● Replant Location ● Existing Tree for Removal



Original Tree Position	Site	Original Tree Species	Confirm Reason for Removal	6 D's	Original Tree Easting	Original Tree Northing	Planting Notes	Replant Species	Replant Easting	Replant Northing
o/s 52	PARK SPRING DRIVE	Prunus sp	Decay	Disease	436254.89	385542.92	TR: Replanting: Malus 'Rudolph' - o/s 52	Malus 'Rudolph'	436254.63	385542.26
o/s 60	PARK SPRING DRIVE	Prunus sp	Decay	Disease	436227.19	385505.51	TR: Replanting: Pyrus calleryana 'Chanticleer' - o/s 60	Pyrus calleryana 'Chanticleer'	436228.51	385506.04
o/s 58	PARK SPRING DRIVE	Prunus sp	Structural Integrity	Dangerous	436249.13	385527.33	TR: Replanting: Malus 'Rudolph' - o/s 58	Malus 'Rudolph'	436248.36	385526.06
o/s 20	PARK SPRING DRIVE	Sorbus aucuparia sp	Senescent	Dying	436238.6	385661.61	TR: Replanting, Liquidambar styraciflua - Plant in wide verge opposite stand of mature Prunus (opposite original position to avoid shading out)	Liquidambar styraciflua 'Worpl	436232.09	385671.55
5th tree from the junction	PARK SPRING DRIVE	Prunus sp	Structural Integrity	Dangerous	436237.04	385660.77	TR: Replanting: Crataegus laevigata 'Paul's Sc' - o/s 20	Crataegus laevigata 'Paul's Sc	436244.98	385664.07