



Park Spring Way o/s 76

East Bank Road

Park Spring Place

Park Spring Drive

PARK SPRING WAY

Scale: 1:500



● Replant Location ● Existing Tree for Removal

© Crown copyright and database rights 2016 Ordnance Survey 100018816

Original Tree Position	Site	Original Tree Species	Confirm Reason for Removal	6 D's	Original Tree Easting	Original Tree Northing	Planting Notes	Replant Species	Replant Easting	Replant Northing
o/s 76	PARK SPRING WAY	Acer pseudoplatanus	Structural Integrity	Dangerous	436166.84	385546.66	TR: Replanting : Acer campestre 'Elegant' - o/s 76	Acer campestre 'Elegant'	436165.3	385546.15